
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02Q027MH	Test ID: <u>D1032-002061</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S02Q027MH
0			Water Level	
4			Dye Test Visible	@ B, 0.2 GPM
4	09	03	Broken	@ jt
4			Abandoned Survey	DYE FLOOD COMPLETE